HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS NO. PA-5608

Vaughn Chevrolet Building (107 East Main Street*(Commercial))
Monongahela
Washington County
Pennsylvania

Photographer:

Mr. Randy Harris

May, 1991

PA-5608-1	View North. South front elevation of original 1883 building on left and c. 1900 side ell addition to the right.
PA-5608-2	View East. West side of elevation of original 1883 building and west side elevation of c. 1890 first rear addition; and the front elevation of the original
	1883 building.
PA-5608 ₋ 3	View North. South front elevation and partial east side elevation of the original 1883 building; and the south front elevation and partial east side
	elevation of the c. 1900 side ell addition.
PA-5608-4	View South. North rear elevation of final rear addition looking from the railroad tracks and Railroad Street.
PA-5608-5	View West. West side and rear elevations of c. 1890 first rear addition; partial north rear elevation of c. 1900 side ell addition; and north rear and
	west side elevation of final rear addition of c. 1940.
PA-5608-6	Second Floor of original 1883 building. View of hall and stair railing looking south toward the front of the building.
PA-5608-7	Second Floor of original 1883 building. View of fire place mantel and trim in living room of front apartment.
PA-5608-8	First Floor of c. 1900 side ell addition. View looking from front entrance to rear of former automotive show room.
PA-5608-9	First Floor of c. 1900 side ell addition. View looking from the service area
	toward rear and into the final c. 1940 rear addition.
PA-5608-10	First Floor of c. 1900 side ell addition. View looking through the opened front
	garage door to the ramp leading to the second floor.

Index to Photographs Vaughn Chevrolet Building (107 East Main Street) HABS No. PA-5608 (Page 2)

PA-5608-11	Second Floor of c. 1900 side ell addition. View looking from the rear of the
	automobile storage area toward the south front and east side corner and
	showing the ramp leading to the first floor.
PA-5608-12	First Floor of c. 1900 side ell addition. View looking from the center of the
	automobile show room area toward the east side elevation.
PA-5608-13	Second Floor of c. 1900 side ell addition. View looking from the center of the
	automobile storage area toward the north east rear corner.
PA-5608-14	First Floor of c. 1940 final rear addition. View in the body shop area looking
	toward the northwest corner of the building.